

93482

RES 20-1808(9-77)

4/7 PAGE 4

LAND CORNER RECORD

T. 4 N, R. 22 W.M. County Corner Code No. 15
 Segregated Surveys:
 Name: Section Corner Corner No.:
 DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

Corner established in July or Aug. 1929 by Capt. Jacob Richardson under his contract No. 437.

Marked origin: 4" Vex post.

20" Hemlock 12' 6" 1st.

16" Hemlock 85' 13" 1st.

1" Hemlock 12' 10" 1st.

2" Hemlock 12' 10" 1st.

2. Description of Evidence Found:

P.S.P.S. 2" Brass cap on 2" Iron pipe 1" above ground.

Orig. 1" now 52" Hemlock 30' 7.2 ft. scribbled visible.

Orig. 1" now 30" Hemlock 12' 10" 1st. 1" 1st. 1st. 1st.

Orig. 1" now 1" Hemlock 12' 10" 1st. 1st. 1st. 1st.

There is no evidence of the corner at record point and distance.

See Mind River Experimental Forest Timber Survey Report - 1953 corner listed as set from original evidence.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No.

3 Page No. 2 Date of work Oct. 1981

Set ground post South with sign 4-4 only.

Walled 4-4 and 12 signs to all 12 signs.

Walls and blazes red.

New bearing trees:

1" Fir 11' 5", 20.0 ft. scribbled 12' 10" 1st.

Blaze and a lower blaze scribbled 12' 10" 1st.

3/4" Brass disk stamped 12' 10" 1st.

1" Hemlock 85' 13", 60.9 ft. scribbled 12' 10" 1st.

Blaze and a lower blaze scribbled 12' 10" 1st.

3/4" Brass disk stamped 12' 10" 1st.

Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 11/15/81

Signature

Certificate No. 16222

AUDITOR'S CERTIFICATE

Filed for record this 18th day of December 1981 at 8:38 AM. In Book 4/7 of Monument at page 4 at the request of

Bishop Surveying, Inc.

H.M. Olson

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

ROLL 121981D
 MARRIAGE APPLICATIONS
 DAILY RECORDINGS
 BOARD OF COUNTY COMMISSIONERS

