

## LAND CORNER RECORD

Skamania

County

T. 4 N. R. 7E, W.M.

Corner Code No. T-13

Segregated Surveys:

Name: One-quarter corner

Corner No.:

DLC, HES, Tract Mining Claim, Indian Allotment, Federal Reserve Townsite

## 1. History of Corner Establishment and Subsequent Restoration.

Corner established in July or Aug. 1895 by Deputy Jacob Richardson under his contract No. 457.

Marked orig. 4" Hemlock post.

7" Hemlock N57W, 18 lks..

9" Yew N40E, 15 lks..

## 2. Description of Evidence Found:

Approx. 30ft. South of proportional corner position, found a 12" Yew down, side facing corner rotted away-scaled 3 ft. circle at indicated corner position. No definite post or discoloration found. Accepted as original BT.

## 3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No.

3. Page No. 11 Date of work Oct. 1981

Set 2"x30" Gal. steel pipe with a 2" Brass cap. No stone available.

Set guard post South with sign 54-4 only.

Nailed BT and 54-4 signs to BT's and painted band and blazes red.

New Bearing Trees:

9" D-Fir N75E, 4.8 ft. scribed S27 upper blaze and a lower blaze scribed BT and with a 3/4"

Brass disk stamped PLS 16337.

8" D-Fir S47W, 16.9 ft. scribed S28 upper blaze and a lower blaze scribed BT and with a 3/4"

Brass disk stamped PLS 16337.

Marked:

T. 4N R. 7E

1/4

S28 S27

1981

PLS 16337

Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

## SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 11/1/81

Signature

Certificate No. 16337

Registered

## AUDITOR'S CERTIFICATE

Filed for record this 18th day of December 1981 at 10:50 A.M. in Book 4/7 of Documents at page 24 at the request of

Bishop Surveying Inc.  
J.M. Olson  
County Auditor