

94733

LAND CORNER RECORD

Skamania

County

T 7 N, R. 6E, W.M.

Corner Code No. A-13

Segregated Surveys:

Name: Section corner

Corner No.:

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Lewis D.W. Shelton in July 1899, & Oct.-Dec. 1900 under Contract No. 552. Set Yew post.

Remonumented by Floyd A. Brooks, Cadastral Surveyor in Oct. & Nov. 1961.

Set Iron post with Brass cap.

Scribed 18" Cedar N31E-25 lks..

Scribed 5" Hemlock N19 1/2 E-36 1/2 lks..

14" Wn. Fir S46 1/2 E-22 lks..

10" Wn. Fir S79E-77 lks..

36" Fir S55 1/2 E-15 lks..

9" Yew S63 1/2 W-43 lks..

8" Hemlock N46 1/2 W-31 lks..

8" Wn. Fir N64W-26 lks..

2. Description of Evidence Found:

BIM Iron post with Brass cap.

Orig. 36" now 43" sawed Fir stump cut below blaze S55 1/2 E-15 lks..

Orig. 18" now 25" sawed Cedar stump N31E-25 lks.-face burned out.

Brooks 9" now 9" Yew snag S63 1/2 W-43 lks. scribing visible on unhealed blaze.

Brooks 10" now uprooted, rotted Wn. Fir stub 1.5 ft. long, no marks remain.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No.

6 Page No. 3 Date of work July 1982

New Bearing Tree:

20" Hemlock stump N51W, 43.9 ft. scribed TMR08333 B1 on face of stump and drove R/R spike in the center.

Set guard post West with sign 54-4 only.

Nailed 54-4 and BT signs to BT's and painted band and blazes red.

There is not a standing tree over 3" in diameter for 500 ft. nor other bearing objects.

Registered [initials] Indexed Dir. [initials]



Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at


SURVEYOR'S CERTIFICATE

94733

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date July 30, 1982

Signature Larry D. Bishop Certificate No. 16337

[SEAL]



AUDITOR'S CERTIFICATE

Filed for record this 14 day of Sep. 1982 at 1:30 P. M. In Book 7/6 of Monuments at page 21 at the request of Larry D. Bishop

Signature Gary M. Olson County Auditor