

94749

LAND CORNER RECORD

Skamania

County

T. 7 N, R. 6E, W.M.

Corner Code No. D-23-24

Segregated Surveys:

Name: Witness Corner

Corner No.:

DLC, HES, Tract, Mining Claim, Indian Adotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

N/A

2. Description of Evidence Found:



N/A

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 6 Page No. 18 Date of work Aug. 1982

Corner falls in the Muddy River-set W.C. East on line 530.10 ft..
Set 2 1/2"x30" Aluminum pipe with a 2 1/2" Aluminum cap in a mound of stone. Marked:

New Bearing Trees:

- 8" Hemlock N16E, 261.5 ft with a square blaze chest high and with a 3/4" Brass disk stamped PLS 16337.
 - 10" Cedar N26E, 266.7 ft. with a square blaze chest high and with a 3/4" Brass disk stamped PLS 16337.
- Set guard post East with sign 54-9 and BM 102 decal. Nailed 54-9 and BT signs to BT's and painted band and blazes red.



Washington Plane Coordinates: Zone, Y X
Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 8/27/82

Signature Larry D. Bishop Certificate No. 16337



AUDITOR'S CERTIFICATE

Filed for record this 14 day of Sept. 1982 at 1:50 P.M. In Book 7/6 of Monument at page 37 at the request of

Signature Larry M. Brown County Auditor