

94750

LAND CORNER RECORD

T. 7 N, R. 6E, W.M. Skamania County Corner Code No. G-23 Segregated Surveys:

Name: One-quarter corner Corner No.: DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

N/A

2. Description of Evidence Found:

N/A

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 6 Page No. 21 Date of work Aug. 1982

Set 2 1/2"x30" Aluminum pipe with a 2 1/2" Aluminum cap. Marked: T.7N R.6E New Bearing Trees: 26" Cedar S3W, 20.0 ft. scribed C/S1 upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped PLS 16337. 7" Hemlock S88E, 12 ft. scribed C/S1 upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped PLS 16337. 1982 Set guard post South with sign 54-9 and BM 102 decals. PLS 16337 Nailed 54-9 and BT signs to BT's and painted band and blazes red.

Washington Plane Coordinates: Zone, Y X Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 8/27/82

Signature Larry D. Bishop Certificate No. 16337

[SEAL]



AUDITOR'S CERTIFICATE

Filed for record this 14 day of Sept 1982 at 1:30 P.M. In Book 7/6 of Monuments at page 38 at the request of

Signature Larry M. Olson County Auditor