

LAND CORNER RECORD

Skamania County
 T 7 N, R 6E, W.M. Corner Code No. A-25
 Segregated Surveys:
 Name: Section Corner Corner No.:
 DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Lewis D.W. Shelton in July 1899, & Oct.-Dec. 1900 under Contract No. 552.
 Remonumented by Floyd A. Brooks, Cadastral Surveyor in Oct. & Nov. 1961.
 Set Cedar post.
 Set 2 1/2" Iron post with Brass cap.
 Scribed 50" Fir N25E-118 lks.. Scribed 9" Fir S27E-35 lks..
 10" Cedar S573/4E-60 lks.. 9" Cedar N15W-8 lks..
 60" Fir S25 1/2 W-50 lks..
 40" Fir N323/4 W-71 lks..

2. Description of Evidence Found:

BIM Brass cap on 2 1/2" Iron post.
 Orig. 50" now 72" Fir N25E-118 lks. healed blaze.
 Orig. 10" now 14" Cedar stump S58E-60 lks. scribing visible.
 Orig. 60" now 75" Fir stump S25W-50 lks. healed blaze.
 Orig. 40" now 56" Fir stump N33W-7 lks. no marks.
 Brooks 9" now 11" Fir S27E-35 lks., blowdown.
 Brooks 9" now 12" Cedar N15W-8 lks., scribing visible.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. _____ Page No. 10 Date of work Aug. 1982

New Bearing Trees:
 12" Cedar S68W, 11.2 ft. scribed T7NR6ES1 upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped PLS 16337.
 10" Cedar S48E, 5.6 ft. scribed T7NR7ES6 upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped PLS 16337.
 Nailed signs 54-4 and BT signs to BT's-painted red band and blazes red on BT's.
 Set guard posts with signs 54-4 and BM 102 decals South & West.

Washington Plane Coordinates: _____ Zone, Y _____, X _____
 Order Accuracy. Derived From: _____
 Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 8/27/82

Signature Larry D. Bishop Certificate No. 16337

[SEAL]



AUDITOR'S CERTIFICATE

Filed for record this 14 day of Sept. 1982 at 1:30 P.M. In Book 7-6 of Monuments at page 43 at the request of

Larry D. Bishop
Greg M. Olson
 County Auditor