

94766

LAND CORNER RECORD

T. 7 N, R. 6E, W.M. Stemania County Corner Code No. K-19
 Segregated Surveys:
 Name: One-sixteenth corner Corner No.:
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

N/A

2. Description of Evidence Found:

N/A

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 2 Page No. 22 Date of work July 1982

Set 2"x30" Aluminum pipe with a 2" aluminum cap. Marked: E. N. 63
 New Bearing Trees: 0
 8" Noble Fir N22E, 30.0 ft. scribed CM1/16S14 upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped PLS 16337. 11/16 S14
 12" Noble Fir S70E, 30.0 ft. scribed CM1/16S14 upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped PLS 16337. 1982
PLS 16337

Set guard posts East and North with sign 54-9 and BM 102 decals.
 Nailed 54-9 and BT signs to BT's and painted band and blazes red.

Washington Plane Coordinates: _____ Zone, Y _____, X _____
 Order Accuracy. Derived From: _____
 Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date JULY 22, 1982
Larry D. Bishop Signature 16337 Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 14 day of Sept. 1982 at 1:30 P. M. In Book 7/6 of monument at page 52 at the request of Larry D. Bishop
Larry M. Olson County Auditor