



# OLSON ENGINEERING

1111 BROADWAY, VANCOUVER, WASH.

PH. (206) - 695-1385

1 KANAKA CR. RD., STEVENSON, WASH.

PH. (509) - 427-8411

BOOK 1/5 PAGE 23

## LAND CORNER RECORD

96817

T 1 N, R 5E, W.M.  
Segregated Surveys:

Skamania

County

Corner Code No. E-19

Name: One quarter corner common to Sections 2 & 11  
DLC, HES MINING CLAIM, INDIAN ALLOTMENT, FEDERAL RESERVE, TOWNSITE

Corner No.

### 1. History of Corner Establishment and Subsequent Restoration; description of Evidence Found:

The 1859 GLO notes call for a 80 inch and a 48 inch diameter fir. Bonneville Power Administration, in about 1939, notes finding a fence corner which has been perpetuated in the same location. However there is neither of the two large trees called for in the GLO notes at record bearing and distance. This corner possibly was set by Clark La Barre around 1910 by chaining 2460 feet from the Northwest Section Corner.

The fence corner is also fairly close to a single proportion. As we could find no two trees to fit the GLO notes, we set the corner by single proportion. The fence corner falls 2.7 feet West and 13.5 feet South.

### 2. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. Page No. Date of work

Set a 3/4" iron pipe with a brass cap from which bears:

R/R spike in 16" Alder w/tag & 3 blazes North 52° East, 11.85 feet.

R/R spike in 20" Fir w/tag & 3 blazes South 26° West, 18.45 feet.

R/R spike in 24" Maple w/tag & 3 blazes North 72° West, 46.29 feet.

Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From

Pin Pointed on Photo No. Date Located at

96817

### SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50 Laws of 1973. Date 26 Feb 80

Signature

Certificate No.

### AUDITOR'S CERTIFICATE

Filed for record this 9th day of Dec. 1983 at 11:50 A.M.  
1/5 of 1000 at Page 23 at the request of Olson Engineering

County Auditor

(Seal)

