

LAND CORNER RECORD

Skamania County
 T 4 N. R 9E W.M. Corner Code No. J-17
 Segregated Surveys:
 Name: Section Corner Corner No.:
 D.L.C., H.E.S., Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

The corner was originally set by Deputy Jacob Richardson during Oct./Nov. 1892 under contract No. 383.

Set post:

Scribed 10" Fir N65E-40 lks..
 9" Fir S88E-34 lks..
 12" Fir S57W-30 lks..
 12" Fir N63W-25 lks..

2. Description of Evidence Found:

DNR 3" Brass cap set in 3" Cement post.
 Orig. BT N63W-16.5 ft. rotting stump scribe visible.
 Orig. BT S57W-18.9 ft. rotting stump scribe visible.
 Orig. BT S88E-22.4 ft. rotting stump scribe visible.



3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 3 Page No. 3 Date of work June 1984

New Bearing Trees:

8" D-Fir N85W-4 ft. scribed T4NR9ES10BT and with a 3/4" Brass disk stamped PLS 16337.

5/8" Iron rod N70E-15.6 feet.

5/8" Iron rod S65E-8.6 feet.

5/8" Iron rod S51W-7.9 feet.

Nailed 54-4 and 54-3 signs to orig. BT stumps and painted bands and blazes red.
 Set guard post 3 ft. South with 54-2a and survey marker decals.

Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date July 1984

Signature *Harry D. Bishop*

16337

Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 24th day of JULY 1984 at 12:10 P.M. In Book 4/9 of MONUMENTS at page 54 at the request of

BISHOP SURVEYING, INC.

William J. Nelson, Dep.
 County Auditor