

STATE OF WASHINGTON  
DEPARTMENT OF NATURAL RESOURCES  
BUREAU OF SURVEYS AND MAPS

BOOK 4/7 PAGE 94

LAND CORNER RECORD

T 4 N, R 7 East, W.M. Skamania County  
Segregated Surveys: Corner Code No. Z-23

Name: Recinds L.C.R. # 96790, dated 1 December 1983 Corner No.: n/a  
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:


Originally set by G.L.O. surveyor, Jacob Richardson, during 1895 G.L.O. survey.  
In 1903, this corner was found by G.L.O. surveyor, Robert F. Whitham during Retracement survey.  
In 1983, the Dept. of Natural Resources set a D.N.R. concrete monument with stamped brass cap at single-proportioned corner position.

2. Description of Evidence Found:

Above described D.N.R. concrete monument with stamped brass cap.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.24 Page No. 52 Date of work 9-25-'84

Reset found D.N.R. concrete monument to newly calculated single-proportioned corner position based on reset northeast corner of Section 1 T.3 N., R.7 E., W.M. Date stamped on brass cap '1984'.  
Corner shown on D.N.R. Final Map # 477.  
See corner diagram on reverse side.



Washington Plane Coordinates: South Zone, Y 166,151.64, X 1,645,511.36  
3rd Order Accuracy. Derived From: Ties to USC & GS Control Stations  
'Greenleaf' and 'Sedum Point'.

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date Jan 15, 1985

Signature M. A. Kinnaman 11977  
Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 21st day of JANUARY 1985 at 12:00 P.M. In Book 4/7 of MONUMENTS at page 94 at the request of Washington State Department of Natural Resources.

J. McLean by J. McLean  
County Auditor

GLO of 1995

West	40.00	set post
	6" fir	N4W 30L
	4" fir	S35E 10L

South  $\frac{1}{4}$  corner, Section 36 T4N R7E

No. 6LO evidence found.

Calc. position falls in a 36" fir stub.

Set RM's as shown.

Both Rm's are on the section line

9-25-84

Gordon  
Bressler  
Hartlin

52  
600.24

