


77031

BOOK 1 PAGE 10

SURVEY OF
SEC. 4, T.1N, R.5E, WM

● SET 3/4" I.P. WITH PLASTIC CAP



ALL BEARINGS & DISTANCES
ARE LAMBERT CONFORMAL
SOUTH ZONE



SURVEYOR'S CERTIFICATE

This map correctly represents a survey made by me or under my direction in
conformance with the requirements of the Survey Recording Act at the request
of REX VALENTINE
in 1973.


Jerry C. Olson
Jerry C. Olson-5025

77031


AUDITOR'S CERTIFICATE

Filed for record this 23 day of July 1974 at 10:45 A.M.
in Book REX VALENTINE at page 10 at the request of

H.P. Tiedt
County Auditor



SET 3/4" I.P. FROM INFORMATION
ON 1941 BONNEVILLE POWER
ADMINISTRATION SURVEY. FOUND
NO TRACE OF WOODEN HUB. THE
STATE HIGHWAY DEPT. SHOWS A
TIE TO THE SAME HUB IN 1937.
THIS POSITION FOR THE CORNER IS
REASONABLY CLOSE TO THE G.L.O.
TOPOGRAPHIC CALLS.



OLSON ENGINEERING
112 E. 13 ST., VANCOUVER, WASH.
PH. (206) 694-9391

Scale: 1"=40' Date: 9/73
Job No. 1332 Calc. By: CLC
Drawn By: CLC
Checked By: CLC
Sheet 1 of 1

