GÁL

LAND CORNER RECORD

(THIS FORM PRESCRIBED BY THE PUBLIC LAND SURVEY OFFICE, DEPARTMENT OF NATURAL RESOURCES, FURSUANT TO RCW 58.09. ALPMA-HUMERIC INCEX DIAGRAM ON THE BACK.)

CORNER INDEXING INFORMATION:

RGE SE CORNER CODE

(Villametta Heridian) (See instructions on back of LCR)

ADDITIONAL IDENTIFIER: (e.g., BLM designation for the corner, street a intersection, plat name, block, lot, etc.)

Br Olson Engineering

308

NORTH!/4 CORNER SECTION 10

COUNTY: -SKAMANKA

AUDITOR'S USE

LAND SURVEYOR INFORMATION: (or Public Officer as per RCW 58.09.090)

This corner record correctly represents work performed by me or under my direction in conformance with the Survey Recording Act.

CCHPANY OR AGENCY: CLSON ENGINEERING INC.

IIII BROADWAY

ADDRESS:

VANCOUVER, WA 98660




WASHINGTON PLANE COORDINATES:

ZONE:

DATUM (Date of adjustment):

CORNER INFORMATION: Use the space below to provide the following information regarding the corner: [1] Pertinent Corner History. (2) Evidence Found at the Corner, and (3) Corner Perpetuation Information. Please title and number the parts of your discussion accordingly. If additional space is needed use the back. (For (3), diagram the references. Also, provide the cross-reference to a map of record, if applicable, the surveyor's field book no /page no . and the date of work.) (See the back of this form for the requirements of the Survey Recording



The original corner post was established on June 4, 1859 by United States Deputy Surveyor, Lewis Van Vleet. Bearing trees were two 60" fir stubs South 11° West, 45 links; and North 2° East, 47 links of which no evidence remains. A 1941 survey by Bonneville Power Administration notes this point as a 1" iron pipe with a brass cap. A Skamania County brass cap was found and tied during previous survey 1-10 which also fits Bonneville Power Administration ties.

This pipe and brass cap's position has been accepted as the corner position.

MARK THE CORNER LOCATION ON THE DIAGRAM BELOW AND FILL IN THE CORNER CODE BLANK ON THE OTHER SIDE: (1) For corners located at the intersection of two lines (Section corners, quarter corners and sixteenth corners):

(a) The corner code is the alpha-numeric coordinate from the diagram below that corresponds to the appropriate intersection of lines.


(2) For commers that are not located at the intersection of two lines (Meander corners, DLC's, HES's, reservation boundaries, mining claims, etc.):

(a) For corners that are on one line only the corner code is the line designation and the related line segment; i.e., a corner on line 5 between "8" and "C" is designated 8C-5.

(b) For corners that are between lines the corner code is both line segments; i.e., a corner in the

SE1/4 of the SE1/4 of section 18 is designated HN-4-5.

8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25



RCW 58.09.060 (2) requires the following information on this form: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) corollary information that may be helpful to relocate or identify the corner position.

SPACÉ FOR ADGITIONAL COMMENT: