AND CORNER RECORD

**B FORM PRESCRIBED BY THE PUBLIC LAND SURVEY OFFICE, DEPARTMENT OF NATURAL
**BOURCES, PURSUANT TO ROW 58.09. ALPHA-MUNIERIC INDEX DIAGRAM ON THE BACK.)

CORNER INDEXING INFORMATION:

TWP 7 NORTH AGE 6 EAST CORNER CODE N-5
(Willemette Meridian) (See Instructions on back of LCR)

ADDITIONAL IDENTIFIER: (e.g. BLM designation for the corner, street intersection,

plat name, block, lot, etc.)

BOOK 165 PAGE 785

FILED FOR RECORD SKAHANIA CO. WASH BY OKON Engineering

FEB 28 | 15 PM '96

AUDITOR

GARY H. OLSON

CARNER COUNTY: SKAMANIA NORTHEAST

LAND SURVEYOR INFORMATION: (or Public Officer as per RCW 58.09.090)

mer record correctly represents work performed I n in conformance with the Survey Recording Act

COMPANY OR AGENCY:

OLSON ENGINEERING, INC. 1111 BROADWAY

ADDRESS:

VANCOUVER, WA 98660


AUDITOR'S USE



WASHINGTON PLANE COORDINATES:

DATUM (Date of adjustment):

CORNER INFORMATION: Use the space below to provide the following information regarding the corner: (1) Pertinent Corner History. (2) Evidence Found at the Corner, and (3) Corner perpetuation information. Please title number the partee of your discussion accordingly. (5) additional appear is needed use the back. (For (3), diagram references. Also, provice the cross-reference to a map of record, if applicables, the surveyor's field book no./page no., the date of work). (See the back of this form for the requirements of the Survey Recording Act). (For (3), diagram the



The original section corner at the Northeast corner of section 19 was a scribed 8" White Fir. south 38° East, 20 Links; A scribed 48" Hemlock, North 6° East, 53 links; A scribed 16" White Fir North 64° West, 24 links; and a scribed 24" White Fir South 60° West, 39 links.

In 1969 the Department of Natural Resources found 3 of the accessories and set a concrete monument with brass cap and new accessories of a 48" Hemlock South 72° West 38.2 feet, a 28" Hemlock North 86° Bast 0.9 feet; a 14" White Fir North 65° West, 24.8 feet and a 16" White Fir South 42° West, 17.1 feet.

In 1995 Olson found the DNR concrete monument still existing.

LAND SURVEYORS ENGINEERS 1111 BROADWAY, VANCOUVER, WA 98660 BOOK 755

HARK THE CORNER LOCATION ON THE DIAGRAM BELOW AND FILL IN THE CORNER CODE BLANK ON THE DIMER SIDE:


(1) For corners located at the intersection of two lines (Section corners, quarter corners and sixteenth corners):

(a) The corner code is the alpha-numeric coordinate from the diagram below that corresponds to the appropriate intersection of lines.

(2) For corners that are not located at the intersection of two lines (Heander corners, DLC's, HES's, reservation boundaries, mining claims, etc.):

(a) For corners that are on one line only the corner code is the line designation and the related line segment; i.e., a corner on line 5 between "8" and "C" is designated 8C-5.

(b) for corners that are between lines the corner code is both line segments; i.e., a corner in the SE'/A of the SEI/A of section 18 is designated MM-4-5.



RCW 58.09.060 (2) requires the following information on this form: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) corollary information that may be helpful to relocate or identify the corner position.

SPACE FOR ADDITIONAL COMMENT: