County: Couner Code No. L-13

## LAWSON LAND SURVEYING

(206) 256-8008

T3 N, R 10E , W.M.;

HARN II LAWSON

THE STATE OF TH

14612 A 4th Plain Rd Vancouver, WA 98662

## LAND CORNER RECORD

Nome: One-quarter corner common to Sections 15 and 16. Corner No. DLC, HES Mining Claim, Indian Allotment, Federal Reserve. Townsite
DIC, MES Mining Claim, Mining William Williams
1. History of Corner Establishment and Subsequent Restoration; description of Evidence Found:
I found no evidence of the 6-inch diameter Dogwood and the 48-inch diameter Fir
called for in the 1875 GLO Notes. However, the Skamania County Road Records show
this corner tied into the March, 1923 survey of Laycock Road. In July, 1925, the
Road was extended past this one-quarter corner and the Road was called the Laycock-
Kelchner Road. These plans also show the East one-quarter corner of Section 16.
The distance West of Laycock-Kelchner Road is shown as 174 feet. On April 13, 1981,
I found the remains of the three-way fence corner (North-South and East) very close
to the position shown on the 1923 and 1925 Road surveys. The vegetation difference
(ie. old field on the West and large timber on the East) plus the condition of the
fence and a large back furrow from years of plowing indicate that this had been the
use line for many years. I re-established the location of the old fence corner and
monumented it as shown in item 2.
Dans and Deposition this Corner Location
2. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location Diagram corner and indicate meridian and reference to map of record.
LAWSON LAND SURVEYING Job # 30 -81 - 160310 : Date of Work: May 1981
Set a 1" galvanized iron pipe with a brass cap and referenced it as follows:
18" diameter Fir North 55° East 30.85 feet.
36" diameter Fir South 21° East 46.12 feet.
Found a 1-inch iron pipe set at single proportion position 83.28 feet East and
2.98 feet North. Old fence bears 6 feet South of the 1-inch iron pipe.
Washington Plane Coordinates: Zone, Y
Order of Accuracy. Derived from:
Pin Pointed on Photo No. Date Located at Located at
SURVEYOR'S CERTIFICATE
The comen record correctly represents work performed
the me or under my direction in compliance with the second
provisions of Chapter 50, Laws of 1973.
Signature On G. Lawren Date June 8 1981
Certificate No. 11989
AUDITOR'S CERTIFICATE
Filed for record this 9 h day of, 1951 at A 15 h.
In book 3/10 of Manual at Page
request of him hambers - Musica dillegange
County Auditor
and the state of t