

92923

RES 20-1808(9-77)

BOOK 6/6

PAGE 15

LAND CORNER RECORD

SKAMANIA

County

Corner Code No. E-21

T. 6 N. R. 6 E W.M.

Segregated Surveys:


Name: NORTHWEST CORNER SECTION TWELVE

Corner No.: NW COR. SEC. 12

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

GOVERNMENT LAND OFFICE SURVEY (1921)



2. Description of Evidence Found:

FOUND OBTS

30" FIR N 30° E 38.28' FACE GROWN, BLM TAG

18" HEMLOCK S 14° E 27.06' FACE GROWN OVER, BLM TAG

MONUMENT DESTROYED BY A SLIDE FROM ROAD CONSTRUCTION

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 151 Page No. 9 Date of work 7-21-81

CREW: ZENKNER
CHASTAIN
NELSON

25" FIR
SIGNS
54-4
54-3

BT
SCRIBED
T6N R6E
S2 BT

6" RED BAND PAINTED AROUND ALL BTS
54-3 & 54-4 SIGNS ON NEW BTS
54-4 SIGNS ON OBTS

SET MONUMENT
IN MOUND OF STONE
SET A 2 1/4" X 30" PIPE
26" INTO GROUND WITH
2 1/2" BRASS CAP MARKED

3' X 2' X 2' RP
STONE
PK NAIL IN TOP

STONE PAINTED
ORANGE

Washington Plane Coordinates: Zone, Y 15 15652 X

Order Accuracy Derived From:

Pin Pointed on Photo No. Date Located at

NOTE! NOTHING AVAILABLE
TO SW FOR BT OR BO. STONE
USED IS SEDIMENTARY AND
WILL NOT HOLD CHISEL MARKS

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date August 10, 1981

Signature

Registered

Indexed, Dir

Indirect

Recorded

Mailed

Certificate No.

AUDITOR'S CERTIFICATE

Filed for record this 13th day of August 1981 at 1:00 P.M. In Book 96 of Monuments at page 15 at the request of

Holla & Associates - Chelate, Wa

By Messenger by A. Davis

County Auditor