

93409

7/5 PAGE 15

LAND CORNER RECORD

T 7 N R 5 E W
 Registered Survey
 Name: **ERST 1/4 CORNER SECTION 20**
 County: **SKAMANIA**
 Corner No: **P-9**

1. History of Corner Establishment and Subsequent Reestablishment
CORNER ORIGINALLY SET BY GOVERNMENT LAND OFFICE SURVEY

2. Description of Evidence Found:

5/8" REBAR 20' LONG 2' OUT OF GROUND

BT

26" FIR N 70 E 24.42 VISIBLE SCRIBE USFS 54-3 SIGN

10" FIR STUB S 58 1/4 W 20.46 VISIBLE SCRIBE USFS 54-3 SIGN

3. Describe Monument, Monument and Corner Data to Determine this Corner's Location in the
 area, corner and its potential and a bearing to monument (USFS 54-3 SIGN) Block No.
161-1 Page No 13 Date of work 11-25-81

**SCRIBED < USFS 54-3 AND
 14520 BT 54-4 SIGN**

BT

**SET A 2 1/2 X 30" GRD
 PIPE 26" IN THE GROUND
 WITH A BRASS CAP
 MARKED T 7 N R 5 E**

**1/4
 S 20 S 21
 1981
 LS 15652**

**14540 49 31'
 34' THEM 100K**

**DISTANCE TAKEN HOYZ FROM
 MONUMENT TO BRASS SURVEY
 TAG LS 15652 NAILED IN TOP
 CIRCLE OF NEWLY SCRIBED "B"**

Painted 6" RED BAND AROUND ALL BTS

Witnessed by the County Auditor
 Order of the Board of Supervisors

By the Board of Supervisors
 Date: **November 30, 1981**

SURVEYOR'S CERTIFICATE

The survey record is hereby reported to be correct and true to the best of my knowledge and belief, and in accordance with the provisions of Chapter 50, Laws of 1972.

Michael G. Hobbs

LS 15652

AUDITOR'S CERTIFICATE

Exhibit forwarded this
 Date: **7/5**

3rd

December

Monuments

Michael G. Hobbs

1981 at 12:45 PM

G.M. Olson
 County Auditor