

93411

LAND CORNER RECORD

SKAMANIA

County

T 7 N R 5 E

Cor. 17 N-7

Segregated Survey

Name: South one-quarter CORNER SECTION 17

Corner No: S 1/4 - 17

1. History of Corner Establishment and Subsequent Restoration

Set by G.L.O.

2. Description of Evidence Found:

Fd 1 1/2" IRON pipe out of position S 38 E 6.60 FT

O.B.T. Fd

26" HEMLOCK N 07 E 22.44 FT visible scribe, wcy. co. tag

26" HEMLOCK S 35 1/2 E 39.27'

3. Describe Monument, Monument and Corner Data: Name of this Corner Location, Date of corner establishment, monument position and description, Surveyor's name, Book No.

161-1 Page 11 Date of work 10-30-81

- Set a 3 1/2" x 30" pipe 26" in ground with brass cap marked

T. T. N. R. S. E.

1 517

4 520

1981

LS 15652

- Painted 6" red bands on O.B.T's

- Nailed 54-3 and 54-4 signs on O.B.T's

Witnessed by _____ Date _____

Established by _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record is a true and correct work performed by me or under my direct supervision and in accordance with the provisions of Chapter 50, Laws of 1975.

November 33, 1981

Michael G. Hobbs

LS 15652

AUDITOR'S CERTIFICATE

Filed for record this 3rd

Book 7/5

of December

of Monuments

10 81 at 12:55 P.M.

at page 17 at the request of

Michael G. Hobbs

D.M. Olson

County Auditor