

7/5 REG 18

93412

LAND CORNER RECORD

SKAMANIA

County

Corner Cbk. No. N-5

T 7 N. R. 5 E W 1/2

Regulated Surveys

Name: Southwest Corner Section 17

Corner No. 3W-17

U.S. G.S. Tract, Mineral Claim, Public Allotment, Federal Land, Town 10

1. History of Corner Establishment and Subsequent Restoration

Set by G.L.O.

2. Description of Each Corner

Ft. Down metal fence post in mound of lava stone

O.B.T. 12" PINE (down snag) S63 1/4 E 23.10 ft visible scribe, old U.S.G.S boundary tag. SAID snag is laying to NW.

3. Discovery Monument, Adjacent and Correlation Data to Correlate this Corner Location. Discovered corner and adjacent monument and survey of corner of Surveyor's Field Book No. 161-1 Page No. 12 Date 11-3-81

Set a 2 1/2" x 30" pipe in mound of lava stone with 4" U.S.G.S pipe has a brass cap marked.


T1N R5E

S18 S17

S19 S20

1981

LS 15652

S4-4, S4-3
6" red band
scribed
T1N R5E S18 BT
C" PINES4-4, S4-3
6" red band
scribed
T1N R5E S17 BT
12" PINE

Witnessed by me, County Auditor, on this 7th day of July, 1981.

Filed for record by David N. [unclear] Date [unclear] Located at [unclear]

SURVEYOR'S CERTIFICATE

This corner record is a true and correct representation of the corner and monument as shown on the survey of the [unclear] and [unclear] with the provisions of Chapter 30, Laws of 1973, dated November 23, 1981.

Michael G. Hobbs

LS 15652

Certificate No.

AUDITOR'S CERTIFICATE

Filed for record this 3rd day of December 1981 at [unclear] at the request of [unclear]

1:00 P.M.

Michael G. Hobbs

Y.M. Olson

County Auditor