

93966

RES 20-1808(9-77)

STATE OF WASHINGTON
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS

LAND CORNER RECORD

3/6 PAGE 14
Also see Sub 1-82
Sub 3/6 Sub 4

T. 3 N. R. 6 East W.M. Skamania County
Segregated Surveys: Corner Code No. E - 15
Name: N/A Corner No. N/A
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Township.

1. History of Corner Establishment and Subsequent Restoration:

Corner not set by original survey, Witness Corner set 0.30 chains
S. 89 59' W. of corner position.

No restoration found.

2. Description of Evidence Found:

Found Witness Corner Tree (now a 15" Fir stump) and two Fir snag
B.T's. See separate L.C.R. for Witness Corner.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.20 Page No. 31 Date of work 7/8/81

Calculated single proportioned position only, no corner set.

Washington Plane Coordinates: South Zone Y 162,080.86 X 1,603,456.88
3rd Order Accuracy. Derived From: USC & GS "Mowich" and USC & GS
"Lookout Mtn. RM # 1"
Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or
under my direction in compliance with the provisions of Chapter
50, Laws of 1973. Date May 11, 1982

Signature

Certificate No.


93966

AUDITOR'S CERTIFICATE

Filed for record this 17 day of July 1982 at M. In
Book 3/6 of Washington State Department of Natural Resources at page 14 at the request of
Washington State Department of Natural Resources.

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2),
Chapter 50, Laws of 1973.



GLO 1903

89-59W ON TRUE LINE

38.50 CREEK BLIS WIDE N.E.

39.87 1/4 COR. FALLS ON ROCK BANK NOT SET.

10.17 20" FIR WITNESS COR.

SCRIBED W.C. 1453 + 1/4 S10

20" FIR S39W 19LKS (W.C. 1453 BT)

29" FIR N20W 33LKS (W.C. 1453 BT)

Witness Corners to the

N 1/4 CORNER S10 T3N R6E


FOUND

15" FIR STUB ATOP ROCK BANK

20" FIR S39W 32' (BT)

24" FIR S39W 22' (BT)

THE WITNESS CORNER TO 1/4 CORNER IS A P.K. AND
IN 15" FIR STUB ATOP ROCK BANK
TOP OF ROCK BANK FALLS ON ROCK BANK
WHEN ALIVE. THE ROCK BANK FALLS ON
ROCK FACE FOR 10' WITNESS CORNER



GLO of 1903

80 00 Set post

" Fir 28" N 47° E 28 L

Fir 30 S 11° 45' E 93 L

Fir 18 S 52° 20' W 57 L

Hemlock 16 N 67° 45' W 62 L

NE corner Section 10 T3N R6E

Found remains (stumps & snags) of 4 BT's.

corner falls within photo search area

Set DPP corner w/ brass cap 3" above ground. Corner is on middle sill post east 3' east of corner. Is a 6' drop off w/ a trailing fir snag on top of drop off.

Hemlock
Garden
Blossom
Wilkin

9-30-80

600.20