

93979

3/8 PAGE 34

T. N. TRANTOW SURVEYING

P.O. Box 287
Bingen, Washington 98605

LAND CORNER RECORD

SKAMANIA

County

T. 3 N. R. 8 E. W.M.

Corner Code No. Q-3

Segregated Surveys:

Name: S-C 1/16 of Section 19

Corner No.:

D.L.C., H.E.S., Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

No record of previous establishment

2. Description of Evidence Found:

No evidence of previous establishment


3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location: Diagram corner and indicate meridian and reference to map of record: Surveyor's Field Book No. 30819 Page No. 48 Date of work April 19, 1982

Set a 1 1/2 x 30" galvanized iron pipe with 2 1/2" brass cap 18" in the ground, from which bear:

8" D-fir, N46W, 5.51 ft. to nail in face on root collar scribed 1/16WT

6" D-fir, S25W, 22.77 ft. to nail in face on root collar scribed 1/16WT

Both trees are marked with SDS Lumber Company witness tags

Registered
Indexed
Indirect
Recorded
Mailed

Washington Plane Coordinates: South Zone, Y 147396.97, X 1656593.12

Third Order Accuracy. Derived From: Skamania County control surveys, 1977

Pin Pointed on Photo No. 92-7 Date SW-74 Located at Trantow Surveying, Bingen

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 17 May 1982

Signature

Certificate No. 15673



AUDITOR'S CERTIFICATE

Filed for record this 18 day of May 1982 at 2:07 P.M. In Book 48 of Trantow Surveying at page 37 at the request of TRANTOW SURVEYING

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.