

HAGEDORN, INC.

"SUITE B"

1924 BDWY. Vancouver, Wash.

Ph. (206) 696-4428

LAND SURVEYORS

Subdivisions, Boundaries, Control, Topography,
Construction Surveys, & Road Layout

1/5 16
LAND CORNER RECORD

Skamania

County

Corner Code No. A-23

T 1 N. R. 5E W.M.

Segregated Surveys

Name Quarter corner common to Sections 1 (1N-5E) & 36 Corner No.

84034

DLC, HES, Tract, Mining Claims, Indian Allotments, Federal Reserve, Townsite

(2N-5E)

1. History of Corner Establishment and Subsequent Restoration:

Wood post in stone mound originally set by Van Fleet and Newsome in 1860 from which a Fir 30 inches bears North 88° West 58.7 feet (89 links). I found a 40 inch rotting stub which is the only likely BT of the correct age in the probable area. At record bearing and 60.3 feet from this tree (no marks visible) I uncovered what appeared to be the remnants of a rock pile with the rotted remains of a wood stake that went down into the rocks in a vertical position, (penetrated approximately 8 inches from present surface). This area has been cat logged and it is very possible that a machine or log has disturbed this evidence. Because the whole area is very rocky the appearance of this rock mound does not differ substantially from natural rock outcrops. However, because it is at record distance and bearing from a likely BT snag, and had a vertical wood stake within the rocks, I feel that this was the original quarter corner. (especially in light of its relationship to adjacent corners East and West). I chained West to check the "call" for the "foot of precipice" and find it to be almost 2 chains long. This is understandable, though, when you consider that Van Fleet was going East, called the top of the bluff (400 feet vertical), and set a flag at the "foot", measured a base 5.00 chains North, and sighted back to top of cliff. He could not possibly have set the "flag" at what we would consider the "foot of precipice" because you cannot see it from the top. Also, since the bluff runs Northeasterly, he could not run a base 5.00 chains North without tunneling into it, let alone sighting back. It becomes obvious that in this case, (and probably the line between 1 and 2 and others) the call for the "foot" is not reliable and the actual point used was several chains out from the base of the cliff. If you measure the record distance West from the quarter corner above described, it falls in a spot that could easily been sighted from above.

Set 5/8 inch iron rod with plastic cap

RPS (with railroad spike at base and metal tag at DBH)

8" Grand Fir North 48° East 10.54 feet.

14" Fir South 37° East 22.11 feet.

20" Fir South 62° West 13.15 feet.

Washington Plane Coordinates: Zone Y X

Order Accuracy. Derived From

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 4-20-82

Signature

12412

Certificate No.

AUDITOR'S CERTIFICATE

Filed for record this 27th day of May 1982 at 3:00 P.M. In Book 1/5 of Monuments at page 16 at the request of

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.