

94275

RES 20-1808(9-77)

USDA
USFS

BOOK 7/5 PAGE 23

LAND CORNER RECORD

T. 7 N. R. 5E W.M. County SKAMANIA
Segregated Surveys: Corner Code No. A-2
Name: NORTH-WEST CORNER SECTION 6 Corner No.
D.L.C., H.E.S., Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

CORNER ORIGINALLY SET BY GOVERNMENT LAND OFFICE SURVEY
RESTORATION IN 1969 BY B.L.M. JAMES E. JELLEY


2. Description of Evidence Found:

BLM MONUMENT WITH BRASS CAP MARKED

OBTS
35" SILVER FIR STUMP N54°50'E 42.24' FACE BROKEN OFF 54-3 SIGN (USFS)
45" HEMLOCK STUMP S112°E 11.89' FACE PARTIALLY GROWN OVER VISIBLE SCRIBE 54-3
33" SILVER FIR STUMP S72°4'W 29.70' NO VISIBLE SCRIBE 54-3 SIGN (USFS)
30" SILVER FIR STUMP N 30°W 36.30' CUT OFF BELOW SCRIBE (REST OF TREE LYING S64°E 41.00'
FROM STUMP - VISIBLE SCRIBE USFS 54-3 SIGN

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 161-1 Page No. 23 Date of work 6-25-82

REFERENCE MONUMENTS ARE
12x30" CAPPED REBAR WITH
LS15652 STAMPED IN TOP
FIBER GLASS GUARD POSTS BEHIND
RM FACING CORNER WITH
USFS 54-3/54-4 SIGNS
ATTACHED.



Washington Plane Coordinates: Zone, Y X
Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973, DCM 25, 1982

Signature: [Signature] Certificate No. 94275

AUDITOR'S CERTIFICATE

Filed for record this 1 day of July 1982 at 11 P.M. In Book 7/5 of [unclear] at page 23 at the request of [unclear]

[Signature] County Auditor