

94736

7/6 PAGE 24

LAND CORNER RECORD

T. 7 N, R. 6E, W.M. County: Shoshone
 Segregated Surveys: Corner Code No. E-13
 Name: Section Corner Corner No.:
 DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Lewis D.M. Shelton in July 1899, & Oct.-Dec. 1900 under Contract No. 552. Remonumented by Floyd A. Brooks, Cadastral Surveyor in Oct. & Nov. 1961.
 Set Cedar post. Set Iron post with Brass cap.
 Scriber 60" Fir N703/4E-48 lks.. Scriber 3" Hemlock S8W-18 1/2 lks..
 54" Fir S473/4E-44 lks..
 22" Cedar S87W-25 lks..
 10" White pine N80W-28 lks..

2. Description of Evidence Found:

BIM 2 1/2" Iron pipe with a 3" Brass cap.
 Orig. 60" now 2" D-Fir healed blaze N71E-48 lks..
 Orig. 54" now 2" D-Fir healed blaze S48E-44 lks..
 Orig. 22" now 28" Cedar stump rotted blaze S87W-25 lks..
 Brooks 3" now 6" Hemlock healed blaze S8W-18 1/2 lks..
 Brooks 5" now 8" Hemlock healed blaze N16W-26 1/2 lks..

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. Page No. Date of work.

Nailed signs 54-1 and 22 signs on BT's, painted red band and blazes red on BT's.
 Set guard posts East and South with sign 54-1 and BIM-102 decals.

Washington Plane Coordinates: Zone, Y, X
 Order Accuracy. Derived From:
 Pin Pointed on Photo No. Date Located at.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date July 30, 1982

Signature Larry D. Bishop Certificate No. 16337

AUDITOR'S CERTIFICATE

Filed for record this 14 day of Sept 1982 at 1:30 P.M. In Book 716 of Monument at page 24 at the request of

Signature Larry M. Olson
 County Auditor