

94754

7/6 PAGE 42

LAND CORNER RECORD

T. 7 N. R. 6E W.M. Skamania County
 Segregated Surveys: Corner Code No. C-21
 Name: One-quarter corner Corner No.:
 DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Lewis
 D.W. Shelton in July 1899, & Oct.-Dec. 1900 under
 Contract No. 552.

Set Cedar post.

Scribed 18" Wh. Fir S86E-41 lks..
 14" Wh. Fir N65W-25 lks..

Remonumented by Floyd A. Brooks,
 Cadastral Surveyor in Oct. & Nov.
 1961.

Set Iron post with Brass cap.

Scribed 8" Hemlock S73E-41½ lks..
 11" Hemlock N44½W-11½ lks..

2. Description of Evidence Found:

BLM Iron post with Brass cap and a 1" Iron pipe.
 Orig. 14" now 18" rotted Wh. Fir stub N65W-25 lks.- no marks remain.
 Brooks 8" now 9" Hemlock S73E-41½ lks.-healed blaze.
 Brooks 11" now 13" Hemlock N44½W-11½ lks.-healed blaze.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 6 Page No. 15 Date of work Aug. 1982

Nailed 54-4 and BT signs to BT's and painted band and blazes red.
 Set guard post North with sign 54-4 only.

Washington Plane Coordinates: Zone, Y X
 Order Accuracy. Derived From:
 Pin Pointed on Photo No. Date Located at.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or
 under my direction in compliance with the provisions of Chapter
 50, Laws of 1973. Date 8/27/82

Signature

Certificate No. 16337

AUDITOR'S CERTIFICATE

Filed for record this 14 day of Sept 1982 at 1:30 P.M. In
 Book 7-6 of monuments at page 42 at the request of

County Auditor

As prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2),
 Chapter 50, Laws of 1973.