


95058

BOOK 3/8 PAGE 35

**LAWSON**

LAND SURVEYING

LICENSED WASHINGTON AND OREGON

(206) 256-8008

JOHN G. LAWSON
Registered Professional Land Surveyor
Registered Professional EngineerY-Plaza
14612-A 4th Plain Rd.
Vancouver, WA 98662

LAND CORNER RECORD

T 3 N, R 8 E, W.M.; Skamania
= county

Corner Code Number: L-21

Page 1 of 1

Corner
Number L-21Name: One-quarter corner common to Sections 13 and 14
DLC, HES Mining Claim, Indian Allotment, Federal Reserve, Townsite

1. History of Corner Establishment and Subsequent Restoration: description of Evidence Found:

There is no evidence left of this corner. This area has burned very hot and the small trees called for in the GLO notes have been destroyed. We set this corner by single-proportionate measurement. DNR concrete monument bears South 28° 38' West, 25.72 feet.

2. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record.

LAWSON LAND SURVEYING Job # 25-82-150308; Date of Work: June, 1982

Set brass cap in 1 inch galvanized Iron Pipe 3 feet long and referenced as follows:

30-inch Douglas Fir, North 30° East, 28.9 feet, scribed "S 13 W 1/2 BT"

9-inch Douglas Fir, South 41° West, 16.1 feet, scribed "S 14 E 1/2 BT"

Washington Plane Coordinates: _____ Zone, Y _____, X _____

Order of Accuracy. Derived from: _____

Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.

Signature John G. Lawson Date Oct 1982Certificate Number 11989

AUDITOR'S CERTIFICATE

Filed for record this 3RD day of Dec, 1982 at 3:40 P.M.
In book 3/8 of MONUMENTS at Page 35 at the request
of LAWSON LAND SURVEYING

95058

J.M. Olson
County Auditor