


95064

87-3/8 PAGE 41



LAND CORNER RECORD

T 3 N, R 8 E, W.M., Skamania
county

Corner Code Number: L-19

Page 1 of 1

Name: Center One-quarter corner, Section 14
DLC, HES Mining Claim, Indian Allotment, Federal Reserve, Townsite
Corner Number L-19

1. History of Corner Establishment and Subsequent Restoration; description of Evidence Found:

This corner falls in the North wheel track of a dirt road. The brass cap is set 6" below ground level.

2. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record.

LAWSON LAND SURVEYING Job # 25-82-150308; Date of Work: June, 1982

Set brass cap in 1-inch galvanized Iron Pipe 3 feet long and referenced as follows:

12-inch Fir, North 74° West, 23.8 feet (scribed)

16-inch Fir, South 72° West, 26.1 feet (scribed)

Washington Plane Coordinates: _____ Zone, Y _____, X _____

Order of Accuracy: _____ Derived from: _____

Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.

Signature: John G. Lawson Date Oct 1982
Certificate Number 11989



AUDITOR'S CERTIFICATE

Filed for record this 3RD day of DEC, 1982 at 4:10 P.M.
In book 3/8 of MONUMENTS at Page 41 at the request
of LAWSON LAND SURVEYING

95064

W.M. Olson by d. New
County Auditor