

95086

BOOK 4/7 1/2 PAGE 10



LAWSON
LAND SURVEYING
LICENSED WASHINGTON AND OREGON
(206) 256-8008
JOHN G. LAWSON
Registered Professional Land Surveyor
Registered Professional Engineer
Y-Plaza
14612-A 4th Plain Rd
Vancouver, WA 98662

LAND CORNER RECORD

T 4 N, R 7 1/2 E, W.M., Skamania
county

Corner Code Number: U-23

Page 1 of 1

Name: Center South One-sixteenth Corner of Section 25
DLC, HES Mining Claim, Indian Allotment, Federal Reserve, Townsite

Corner
Number U-23

1. History of Corner Establishment and Subsequent Restoration; description of Evidence Found:

2. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record.

LAWSON LAND SURVEYING Job # 28-82-250407 1/2; Date of Work: September, 1982

Set a 2-inch diameter aluminum pipe and cap and referenced it as follows:

7-inch Douglas Fir, North 56° East, 7.4 feet, scribed "S-25 CS 1/16 BT"

7-inch Douglas Fir, South 72° West, 21.8 feet, scribed "S-25 CS 1/16 BT"

Washington Plane Coordinates: _____ Zone, Y _____, X _____

Order of Accuracy: _____ Derived from: _____

Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.

Signature John G. Lawson Date Oct 1982

Certificate Number 11989



AUDITOR'S CERTIFICATE

Filed for record this 3RD day of DEC, 1982 at 5:00 PM.

In book 4/7 1/2 of MONUMENTS at Page 10 at the request of LAND SURVEYING - LAWSON

95086

J.M. Olson by A. Davis
County Auditor