

95288

LAND CORNER RECORD

SKAMANIA

County

T 4 N R 9 E W.M.

Corner Co. No. U-20

Surveyor: Surveyor:

Name: SOUTH EAST 1116

Corner No.:

1. History of Corner Establishment and Subsequent Restoration:



N/A

2. Description of Evidence Found:

N/A

3. Describe Monument, Accession and Correlate Data to Perpetuate this Corner Location: Diagram corner and indicate monument and reference to map of record. Surveyor's Field Book No. 5 Page No. 16 Date of work 12/82

SET A 2 1/2" x 30" ALUM. PIPE WITH A 2 1/2" ALUM. CAP.



Washington Plane Coordinates:

Zone: Y

X

Order Accuracy: Derived From:

Pin Pointed on 4 in to No.

Date:

Located at:

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction, in compliance with the provisions of Chapter 59, Laws of 1973. Date 1-6-1983

Signature: Roy O. Gaylord

Certificate No. 18731

95288



AUDITOR'S CERTIFICATE

Filed for record this 17th day of January 1983 at 10:40 A.M. in Book 4/9 of Monuments at page 28 at the request of Terra Surveying

Mary M. Olson by B. Babcock

County Auditor