

95216

3/8 PAGE 53

T. N. TRANTOW SURVEYING

P.O. Box 287
Bingen, Washington 98605

LAND CORNER RECORD

SKAMANIA

County

T. 3 N, R. 8 E, W.M.

Corner Code No. U-1

Segregated Surveys:

Name: S1/16 between Sections 25 3/7 1/2 & 30 3/8

Corner No.:

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

IP apparently set by Longview Fibre Co. circa 1968; IP set by unknown party after that date.

2. Description of Evidence Found:

3/4" iron pipe, S54E, 0.76 ft. from new corner set (LF CO.)
3/4" iron pipe, N46W, 5.50 ft. from new corner set (unknown)
Neither pipe was accepted for corner

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 30819 Page No. 45 Date of work February 15, 1982.

At the position determined, set a 1 1/2 x 30" galvanized iron pipe with 2 1/2" brass cap, 26" in the ground, from which bear:

36" red cedar, S73E, 25.24 ft. to face scribed 1/16WT. Marked with LF Co. tags
40" red cedar, S09W, 30.41 ft. to LF Co. witness tag. Not scribed
Old LF Co. IP, S54E, 0.76 ft.
3/4" IP, 18" above ground, N46W, 5.50 ft.Washington Plane Coordinates: south Zone Y 142242.15, X 1653946.25
third Order Accuracy. Derived From: Skamania County control surveys, 1977

Pin Pointed on Photo No. 92-6 Date SW-74 Located at Trantow Surveying, Bingen

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 21 February 1982

Signature

Certificate No. 15673

95216

AUDITOR'S CERTIFICATE

Filed for record this 20th day of JANUARY 1983 at 12:30 P.M. In Book 3/8 of MONUMENTS at page 52 at the request of TRANTOW SURVEYING

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.