

96488

RES 20-1808(9-77)

3/8 PAGE 66

LAND CORNER RECORD

Skamania County
 T 3 N, R 8 East, W.M. Corner Code No. A-7
 Segregated Surveys:
 Name: n/a Corner No.: n/a
 DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:
 Originally set by G.L.O. surveyor, Robert A. Webster, in 1896.
 No restoration found.

2. Description of Evidence Found:
 22" Fir B.T. with visible scribe at N 41 E, 11.30 feet from corner position.
 32" Fir B.T. with visible scribe at S 33 E, 15.23 feet from corner position.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.22 Page No. 1 Date of work 12-8-82

Shown on D.N.R. Final Map #462. See corner diagram on reverse side.

On 12-8-82, the D.N.R. set a standard D.N.R. iron pipe with stamped brass cap at intersection of G.L.O. distance from B.T. faces.

Washington Plane Coordinates: South Zone Y 166,597.14 X 1,662,167.88
 3rd Order Accuracy. Derived From: 1975 Olson Eng. survey data at S.W. corner Sec. 5 (Recorded in Bk 1 page 54, Records of Skamania County)
 Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date Sept. 29, 1983

Signature: M. A. Kusan Certificate No. 11977




AUDITOR'S CERTIFICATE

Filed for record this 6th day of OCTOBER 1983 at 1:30 P.M. In Book 3/8 of MONUMENTS at page 66 at the request of Washington State Department of Natural Resources

J. M. Olson by J. M. Olson, Dep.
 County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.



610 of 1896
 East on north boundary of Sec 5
 39.09 Creek 1 link wide flows SW
 40.00 Set a post --
 Fir 12" S 33° E 23 L. 15.18
 Fir 12" N 35° E 16 L. 10.56
 42.33 steep descent
 1/4 corner S 32° T 4° N E 8° E, W. M.
 Found - 2 live bearing trees. I cut
 into both and saw scribbling on both.
 Corner pt. was established by intersecting
 610 dist from BT faces. Found discolored
 soil white digging hole - possibly post remnants
 ground level
 No other surveys of record
 corner is station # 199 - see pg 40 for tie

Nov 2, 1902
 Dec 8, 1902

Laird
 Gordon
 8133 for
 Island