

96503

RES 20-1808(9-77)

Doc 2/5 PAGE 31

LAND CORNER RECORD

T. 2 N, R. 5 East, W.M. Skamania County
 Segregated Surveys: Corner Code No. V-1
 Name: n/a Corner No.: n/a
 DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

Originally set by John Truten during 1857 G.L.O. survey. Restored in 1908 with Skamania County iron pipe and cap. County records indicate that 2 B.T. snags were found during 1908 survey. Pipe used in 1971 unrecorded Dept. of Game survey and 1979 Alpha Engineers survey filed in Book 10 page 199.

2. Description of Evidence Found:

Above mentioned Skamania County iron pipe and cap set in a monument case 3" below surface of Alder Road, 63.8 ft south of centerline of Buhman Road and 34.6 ft West of Line Crossing Post. Held for corner. Accepted corner.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 607.07A Page No. 17 Date of work 20 Jan '82

Shown on D.N.R. Final Map 441
 See sketch on back.

Washington Plane Coordinates: South Zone Y 110,075.78 X 1,552,799.66
 3rd Order Accuracy. Derived From: USC & GS 'Ells' and DNR 3-3N-4E

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date Sept 27, 1983

Signature

11977

Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 27th day of OCTOBER 1983 at 2:45 P.M. In Book 2/5 of MONUMENTS at page 31 at the request of Washington State Department of Natural Resources

H. M. Olson Jr. D. Davis, Rep.
 County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

