

96694

### FORM OF CLAIM FOR DAMAGES

TO THE BOARD OF COUNTY COMMISSIONERS of Skamania County, Washington:


PLEASE TAKE NOTICE that in accordance with Chapter 36.45 of the Revised Code of Washington, I Lernard Knigert hereby present you with my claim for damages against the County of Skamania, State of Washington, with the information required to be given by RCW 36.45.020 as follows:

1. That the injury for which I claim damages against the County of Skamania, State of Washington, occurred on or about the 11-2 day of 1983

2. That the place of injury was Sand Hill

3. That the location and description of the defect which caused the injury are Tree across road

4. That the injury is described as follows:



5. That the amount of damages claimed is as follows: \$ 594.08

6. That the actual residence of the claimant at the time of presenting and filing this claim is Box 621 Carson WA 98610

7. That the actual residence of the claimant for a period of six months immediately prior to the time that this claim accrued was \_\_\_\_\_

DATED: 11-18-83, 19 \_\_\_\_\_

Lernard Knigert  
(Claimant)

**B & S FRAME & BODY**  
 10 RAND ROAD  
 MOORE RIVER, OR 97031  
 386-4039

AS LISTED FOR LABOR AND MATERIALS  
 VERBAL AGREEMENTS NOT BINDING - ESTIMATES FREE

No. *Shawanda County*      **ESTIMATE OF REPAIRS**

Owner *Ed Knight*      Date *11-4-83*

Address *P.O. Box 631*      Phone *497-5741*      Est. No. *8*

*Carson*      Order No. *8*

YEAR <i>78</i>	MAKE <i>Dodge</i>	MODEL <i>Caravan</i>	LICENSE NO. <i>ENF507</i>	SPEEDOMETER:	Retain Parts	Destroy Parts
-------------------	----------------------	-------------------------	------------------------------	--------------	--------------	---------------

QUAN.	DESCRIPTION OF LABOR OR MATERIAL	*	PART NO.	MATERIAL	LABOR
	Replace front bumper			172.68	1.8
	Replace <sup>10131</sup> center type <sub>4.19</sub>			109.50	5
	Turn signals			10.56	2
	Repair RR Door				3.0
	RR Door				1.0
	RR GTR				2.0
	adjust hood & header				1.0
	Replace RR bumper filler			19.00	2
	repair header panel to end				1.0
	<del>repair front bumper</del>				
	Repair bottom oil case suppt				2.0
	adjust front bumper				5
	repair fins on A.C. condenser				5
	RR Door 2.0			51.00	5.1
	RR GTR 2.4				
	spot header panel 1.5				
					1.9
					8
					5.1

Old parts removed from cars will be junked unless otherwise instructed.  
 The above is an estimate based on our inspection and does not cover additional parts or labor which may be required after the work has been opened up. Occasionally after work has started worn parts are discovered which are not evident on first inspection. Because of this the above prices are not guaranteed.

Estimated By <i>[Signature]</i> Estimate Approved By	TOTAL MATERIAL		
AUTHORIZED AND ACCEPTED      You are hereby authorized to make the above specified repairs.  By Owner or Agent _____      Date _____	Total Labor	18.5	413.66
	Total Material		555.74
	Tax		
	Paid Out-Tow & Storage		
Sublet Repairs			
<b>TOTAL</b>			<b>572.34</b>

# OWEN CHEVROLET-OLDSMOBILE, Inc.

3100 West Cascade • P. O. Box 177 • Phone 386-3311  
HOOD RIVER, OREGON 97031

## ESTIMATE OF REPAIRS

No. \_\_\_\_\_


CHEVROLET

OLDSMOBILE

SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_ SHEETS

NAME <i>Ed Knight</i>		ADDRESS <i>P.O. Box 62, Casson, Va</i>			DATE <i>11-4-83</i>
MAKE OF CAR <i>Dodge</i>	YEAR <i>76</i>	TYPE <i>Corona</i>	LICENSE NO. <i>EVES02</i>	MILEAGE <i>24293</i>	MOTOR NO. <i>W141K6A204964</i>
INSURED BY	ADJUSTER	INSPECTOR	PHONE HOME BUSINESS <i>4275741</i>		CAR LOCATED AT

DESCRIPTION OF REPAIRS AND REPLACEMENTS	PARTS		LABOR AMOUNT	PAINT AMOUNT	TOTAL AMOUNT
	NUMBER	AMOUNT			
<i>Replace Full Grille .5</i>		<i>107.31</i>	<i>4.60</i>		
<i>Replace LT FWT Signal Lens 2</i>		<i>9.67</i>	<i>14.60</i>		
<i>Hoood Flood 2-0</i>			<i>46.00</i>		
<i>Repair Rt Rear Door 2-0</i>			<i>137.00</i>		
<i>Repair Rt Rear 1/4 6-0</i>			<i>137.00</i>		
<i>Refresh Damage Area 5-0</i>			<i>115.00</i>	<i>30.00</i>	
					<i>594.00</i>



TOTAL			
WRECKER SERVICE			
TAX			
TOTAL ESTIMATE			
INSURED PAYS		INS. CO. PAYS	R.O. No.
\$		\$	
INS. CHECK PAYABLE TO			

The above is an estimate, based on our inspection, and does not cover additional parts or labor which may be required after the work has been opened up. Occasionally, after work has started, worn, broken or damaged parts are discovered which are not evident on first inspection. Quotations on parts and labor are current and subject to change.

EST. MADE BY: *[Signature]*  
AUTHORIZATION FOR REPAIR: *[Signature]*

SIGNED: \_\_\_\_\_ DATE: \_\_\_\_\_