



OLSON ENGINEERING

1111 BROADWAY, VANCOUVER, WASH.

PH. (206) - 695-1385

1 KANAKA CR. RD., STEVENSON, WASH.

PH. (509) - 427-8411

BOOK 1/5 PAGE 24

LAND CORNER RECORD

96318

T 1 N, R 5E, W.M.

Skamania

County

Corner Code No. E-17

Segregated Surveys:

Name: Corner common to Sections 2, 3, 10 & 11

Corner No.

DLC, HES MINING CLAIM, INDIAN ALLOTMENT, FEDERAL RESERVE, TOWNSITE

1. History of Corner Establishment and Subsequent Restoration; description of Evidence Found:

Found a Skamania County Brass Cap in East-West fence line. A 48" diameter fir stub bears North 18° West, 134 feet. A 30" fir stump bears South 41° West, 134 feet. The two distances do not exactly match the GLO record and it looks like someone averaged the error between the two stumps. The 48 inch diameter tree is gone unless he miscalled the bearing to a 70" diameter fir snag.

2. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. Page No. Date of work

Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From

Pin Pointed on Photo No. Date Located at

96318

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 26 Feb 80

Signature

Certificate No. 11989

AUDITOR'S CERTIFICATE

Filed for record this 9th day of 1000 1983 at 11:50 A.M. of 1/5 of Monument at Page 24 at the request of Olson Engineering

County Auditor

