
Corner No.:



T. N. TRANTOW SURVEYING

412 W. Jefferson P.O. Box 287

Bingen, Washington 98605 (509) 493-3111

LAND CORNER RECORD

T 3 N, R 10 E , W.M. KLICKITAT & County Corner Code No. A-13 SKAMANIA

Name: Cor. to 33 & 34, T4NR 10E & 3 & 4, T3NR 10E

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration: 2. Description of Evidence Found: GLO in 1875 set a post for this corner, from which bear: 8" dogwood, N68E, 8 links (5.28 ft.) 30" fir, N65W, 13 links (8.58 ft.) 6" fir, S50W, 34 links (22.44 ft.) 10" fir, S55E, 32 links (21.12 ft.) DNR in 1963 found the S.3 BT and set a concrete monument, from which bear: 20" grand fir snag, \$55E, 21.12 ft. 12" D-fir, S9°30'W, 15.65 ft., scribed R.B.T. Both trees marked with DNR witness tags.

2. Found monument as described, in a mound of stone, from which: 20" grand fir, dead & down and badly rotted, with "National Forest" sign 14" D-fir with healed face and DNR witness tag A fenceline runs south and east from this corner.



3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. F.B. No. 31.003 Page No. 43 Job No. 83121 Date of Work December 1, 1983

From the 4x4 concrete monument, set 18" in the ground, in a 12x12x6" mound of stone, bear: 14" D-fir, S12W, 17.18 to center of tree with healed face and DNR witness tag 20" grand fir windfall, S53E, 22.11 ft. to center of rotted remains 14" white fir, N29W, 59.00 ft. to center of tree scribed on root crown S33WT 18" D-fir, N25E, 63.19 ft. to center of tree scribed on root crown S34WT 16" D-fir, S7E, 26.45 ft. to center of tree scribed on root crown S3WT New witness trees marked with aluminum witness tags. Corner is 25 ft. south of centerline of a gas line.



Washington Plane	Coordinates:	South Zone,	y NA	X		
	r Accuracy. De		*			
%	in a second	.0.0			1 (19.3	٠
	1. 0.	- 1/3/1/ -	7.0		- D	

Pin Pointed on Photo No. 4-9 Symbol KYK-79 Located at Trantow Surveying, Bingen

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter

50, Laws of 1973... Signature

Certificate No. 15673



AUDITOR'S CERTIFICATE

Filed for record this 24 TH day of JANUARY 1964 at 9:30 of MUNUMENTS at page 3.5 at the request of

T. N. TRANTOW SURVEYING

