

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

Skamania County

T 3 N, R 6 E, W.M.

Corner Code No. A-15

Segregated Surveys:

Name: N/A

Corner Number: N/A

1. History of Corner Establishment and Subsequent Restoration: Originally set by G.L.O. Surveyor, Robert F. Whitham, during 1903 survey.

2. Description of Evidence Found:

- 1 60" fir snag with visible scribing at N18°W - 33.0 feet.
1 24" rotted hemlock stump at S18°E - 42.0 feet.



3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.23, Page No. 55. Date of work 8-4-83.

Shown on D.N.R. F.M. #489

See corner diagram on reverse side.

Set std. D.N.R. iron pipe
with stamped brass cap
from 2 found B.T.'s.

Washington Plane Coordinates: South Zone, Y 166,369.70, X 1,603,520.89
Third Order Accuracy. Derived from ties to "Swanberg Photo Control" Tgt's 100 & 101.
Pin Pointed on Photo No. _____, Date _____, Located at _____.

SURVEYOR'S CERTIFICATE

[Seal]:

This corner record correctly represents work
performed by me or under my direction in compliance
with the provisions of Chapter 50, Laws of 1973.
Date 2-6-84.

H. Thomas Land Jr.
Signature

21490
Certificate No.

AUDITOR'S CERTIFICATE

Filed for record this 9TH day of FEBRUARY 1984 at 1:15 P.M.
In Book 3/6 of MONUMENTS at page 22 at the request
of Washington State Department of Natural Resources.

21
X

H.M. Olson by d. New, Rep
County Auditor



620 OF 1903

40.00 Set Post

24" Hemlock S18 E 65 L

60" Fir N18 W 50 L

1/4 CORNER

$\frac{34 \text{ TAN}}{3 \text{ TSN}} \text{ R6E}$

FOUND: 60" fir snag with scribing
24" rotted hemlock stump


WILLIS
SCHAFER SS
600.23

LAIRD
GORDON
DRESSLER
WATKINSON
GOODWAY

8-4-83

T4N
R6E
 $\frac{1}{4} \text{ S } 34$
T3N

60" Fir
BT Snag
Visible Service



SET DNR PIPE & CAP ON STEEP SW slope.
Cap is 4" above ground, placed stones around
pipe