

97105

BOOK 4/6 PAGE 1

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

Skamania County

T 4 N, R 6 E, W.M.

Corner Code No. Z-15

Segregated Surveys:

Name: N/A

Corner Number: N/A

1. History of Corner Establishment and Subsequent Restoration: Originally set by G.L.O. Surveyor, Robert F. Whitham, during 1903 survey.

2. Description of Evidence Found:

- 1 60" fir snag with visible scribing at N18°W - 33.0 feet.
1 24" rotted hemlock stump at S18°E - 42.0 feet.



3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.23, Page No. 55. Date of work 8-4-83.

Shown on D.N.R. F.M. #489

See corner diagram on reverse side.

Set std. D.N.R. iron pipe
with stamped brass cap
from 2 found B.T.'s.

Washington Plane Coordinates: South Zone, Y 166,369.70, X 1,603,520.89
Third Order Accuracy. Derived from ties to "Swanberg Photo Control" Tgt's 100 & 101.
Pin Pointed on Photo No. _____, Date _____, Located at _____.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.
Date 2-6-84.

Signature

21490

Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 9TH day of FEBRUARY 1984 at 1:15 P.M.
In Book 4/6 of MONUMENTS at page 1 at the request
of Washington State Department of Natural Resources.


J. M. Allen
County Auditor

WILLIS
SCHAFER SS
600.23

LAIRD
GO ROON
BRESSLER
MARTINSON
600.23

8-21-83

1/4 S 34
T 3 N
1983



670 0 R 1903

40.00 Set Post

24" Hemlock S18 E 65 L

60" Fir N18 W 50 L

1/4 CORNER 34 THN 3 T 3 N R 6 E

FOUND: 60" Fir snag with scribbing
24" rotted hemlock stump