

97109

BOOK 3/6 PAGE 28

State of Washington  
 DEPARTMENT OF NATURAL RESOURCES  
 BUREAU OF SURVEYS AND MAPS  
 LAND CORNER RECORD

Skamania County

T 3 N, R 6 E, W.M.

Corner Code No. A-23

Segregated Surveys:

Name: N/A

Corner Number: N/A

1. History of Corner Establishment and Subsequent Restoration: Originally set by G.L.O. Surveyor, Robert F. Whitham, during 1903 survey.

2. Description of Evidence Found:

None.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 60G.23A, Page No. 6. Date of work 9-27-83.

Shown on D.N.R. F.M. #489

See corner diagram on reverse side.

Set a P.K. nail in 30" fir root, at a position on line between 1/4  $\frac{25}{2}$  and N.E. corner, Sec. 1 and at the G.L.O. 40 chain ridge-top position.

Washington Plane Coordinates: South Zone, Y 166,142.82, X 1,614,022.94  
 Third Order Accuracy. Derived from ties to "Swanberg Photo Control" Tgt's 100 & 101.  
 Pin Pointed on Photo No. \_\_\_\_\_, Date \_\_\_\_\_, Located at \_\_\_\_\_.

## SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.  
 Date 2-6-84.

Signature

*H. Thomas Laird Jr.*21490  
Certificate No.

[Seal]



## AUDITOR'S CERTIFICATE

Filed for record this 9th day of FEBRUARY 1984 at 11:15 P.M.  
 In Book 3/6 of MONUMENTS at page 28 at the request  
 of Washington State Department of Natural Resources.

X  
 X

*J. M. Olson* by *J. News, Rep.*  
 County Auditor

# GLO Survey of 1903

40.00 Top of ascent - a ridge bears N 45° E.

Set a larch post -- from which:

A Fir 24" S 11° 45' E 41 lks.

A Fir 30" N 10° 30' W 45 lks.

1/4 corner  $\frac{S. 36}{S. 1}$  T 36 4 N R 6 E


Found no original evidence.

Set corner on line between the 1/4  $\frac{35}{2}$  and  $\frac{36}{11}$ , both found GLO corners, and on top of the ridge. The ridge top was mapped in the field prior to setting corner.

6  
600.139

Laird  
B. Nether-ton

9-27-83



Corner is a PK nail in the northwesterly root of a 30" Fir snag. Corner is in a patch of timber on a south slope of a N-S ridge. There is a flat clearing and rock outcrop 40 ft north and a rock outcrop 35' south of the corner.