

97110

BOOK 4/6 PAGE 5

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

Skamania County

T 4 N, R 6 E, W.M.

Corner Code No. Z-23

Segregated Surveys:

Name: N/A

Corner Number: N/A

1. History of Corner Establishment and Subsequent Restoration: Originally set by G.L.O. Surveyor, Robert F. Whitham, during 1903 survey.

2. Description of Evidence Found:

None.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.23A, Page No. 6. Date of work 9-27-83.

Shown on D.N.R. F.M. #489

See corner diagram on reverse side.

Set a P.K. nail in 30" fir root, at a position on line between $1/4 \frac{35}{2}$ and N.E. corner, Sec. 1 and at the G.L.O. 40 chain ridge-top position.

Washington Plane Coordinates: South Zone, Y 166,142.82, X 1,614,022.94
Third Order Accuracy. Derived from ties to "Swanberg Photo Control" Tgt's 100 & 101.
Pin Pointed on Photo No. _____, Date _____, Located at _____.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.
Date 2-6-84.

H. Thomas Laird Jr.
Signature

21490

Certificate No.

[Seal]



AUDITOR'S CERTIFICATE

Filed for record this 9TH day of FEBRUARY, 1984 at 1:15 P.M.
In Book 4/6 of MONUMENTS at page 5 at the request
of Washington State Department of Natural Resources.

G.M. Nelson by A. Davis, Rep.
County Auditor

GLO Survey of 1903

40.00 Top of ascent - a ridge bears N 45° E.

Set a larch post -- from which:

A. Fir, 24" S 11° 45' E 41 lks.

A. Fir 30" N 16° 30' W 45 lks.

1/4 corner S. 36 T 36 4 N R 6 E

Found no original evidence.

Set corner on line between the $\frac{1}{4}$ $\frac{35}{2}$ and $\frac{34}{1}$, both found GLO corners, and on top of the ridge. The ridge top was mapped in the field prior to setting corner.

