

97111

BOOK 3/6 PAGE 30

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

Skamania County

T 3 N, R 6 E, W.M.

Corner Code No. C-21

Segregated Surveys:

Name: N/A

Corner Number: N/A

1. History of Corner Establishment and Subsequent Restoration: Originally set by G.L.O. Surveyor, Robert F. Whitham, during 1903 survey.

2. Description of Evidence Found:

None.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.23A, Page No. 9. Date of work 9-27-82.

Shown on D.N.R. F.M. #489

See corner diagram on reverse side.

Set std. D.N.R. iron pipe with stamped brass cap at single-proportioned position.

Washington Plane Coordinates: South Zone, Y 164,511.22, X 1,611,372.48.
Third Order Accuracy. Derived from ties to "Swanberg Photo Control" Tgt's 100 & 101.
Pin Pointed on Photo No. _____, Date _____, Located at _____.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.
Date 2-6-84.

H. Thomas Land
Signature

21490

Certificate No.

[Seal]



AUDITOR'S CERTIFICATE

Filed for record this 9TH day of FEBRUARY 19 84 at 1:15 P.M.
In Book 3/6 of MONUMENTS at page 30 at the request
of Washington State Department of Natural Resources.


St. M. Olson by L. Neri, Dep
County Auditor

9
60023A


GORDON
BRESSLER
LAIRO

9-27-82

1/4 SEC 18
R6E
T483
NEL



NORTH
12.09



SET PIPE WITH A BRASS CAP 5"
ABOVE GROUND @ CALC. POSITION.
CORNER IS IN A SHALLOW DRAW
WHICH RUNS S.E.

GLO 1703
25.37 CHAINS SOUTH; SET POST NY448
18" DEAD LARCH S 32-30E 38L
12" DEAD LARCH N 36-45W 21L

1/4 CORNER S 24 S 1 T 3 N R 6 E

FOUND NO TRACE ORIG
CORNER