

97112

BOOK 3/6 PAGE 32

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

Skamania County

T 3 N, R 6 E, W.M.

Corner Code No. A-21

Segregated Surveys:

Name: N/A

Corner Number: N/A

1. History of Corner Establishment and Subsequent Restoration: Originally set by G.L.O. Surveyor, Robert F. Whitham, during 1903 survey.

2. Description of Evidence Found:

None.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.23A, Page No. 12. Date of work 9-27-83.

Shown on D.N.R. F.M. #489

See corner diagram on reverse side.

Set std. D.N.R. iron pipe with stamped brass cap at single-proportioned position.

Washington Plane Coordinates: South Zone, Y 166,169.66, X 1,611,407.75
Third Order Accuracy. Derived from ties to "Swanberg Photo Control" Tgt's 100 & 101.
Pin Pointed on Photo No. _____, Date _____, Located at _____.


SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.
Date 2-6-84.

Signature

*H. Thomas Lord Jr.*21490
Certificate No.**AUDITOR'S CERTIFICATE**

Filed for record this 9th day of FEBRUARY 1984 at 1:15 P.M.
In Book 3/6 of MONUMENTS at page 32 at the request
of Washington State Department of Natural Resources.



J. M. Olson by A. Newb. Dep.
County Auditor

12
6003A

Gordon
Bressler

9-27-83

GLO 1903

8000 Set Post 4x4x48"

48" fir N71E 56L


28 Hem. S63E 100L

13" Hem S56 30W 16L

24" Cane N69W 78L

Section Cor. $\frac{3536}{211}$ T4N R6E

Found no orig. evidence



SET Pipe with D.N.R. BRASS CAP
5" ABOVE GROUND @ CALC. POSITION
A SMALL DRAW 30'-40' EAST OF CORNER
RUNS SOUTH