

State of Washington
 DEPARTMENT OF NATURAL RESOURCES
 BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

Skamania County

T 4 N, R 6 E, W.M.

Corner Code No. Z-21

Segregated Surveys:

Name: N/A

Corner Number: N/A

1. History of Corner Establishment and Subsequent Restoration: Originally set by G.L.O. Surveyor, Robert F. Whitham, during 1903 survey.

2. Description of Evidence Found:

None.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.23A, Page No. 12. Date of work 9-27-83.

Shown on D.N.R. F.M. #489

See corner diagram on reverse side.

Set std. D.N.R. iron pipe
 with stamped brass cap at
 single-proportioned position.

Washington Plane Coordinates: South Zone, Y 166,169.66, X 1,611,407.75
 Third Order Accuracy. Derived from ties to "Swanberg Photo Control" Tgt's 100 & 101.
 Pin Pointed on Photo No. _____, Date _____, Located at _____.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.
 Date 2-6-84.


Signature

H. Thomas Laird Jr.

21490

Certificate No.

[Seal]

**AUDITOR'S CERTIFICATE**


Filed for record this 9th day of FEBRUARY 1984 at 1:15 P.M.
 In Book 4/6 of MONUMENTS at page 7 at the request
 of Washington State Department of Natural Resources.

J. M. Nelson
 County Auditor

GORDON
BRESSLER

12
600.23A

9-27-83



SET PIPE WITH D.N.R. BRASS CAP
5" ABOVE GROUND @ CALC. POSITION
A SMALL DRAW 30'-40' EAST OF CORNER
RUNS SOUTH

GLO 1903

89.00 Set Post 4"x4"x48"

48" fir N 71° E 56 L

28 Hem. S 63° E 100 L

13" Hem S 56° 30' W 16 L

24" LARCH N 69° W 78 L

Section Cor. 3536 211

T4N R4E

Found no orig. EVIDENCE