

97116

BOOK 3/6 PAGE 36

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

Skamania County

T 3 N, R 6 E, W.M.

Corner Code No. A-25

Segregated Surveys:
Name: N/A

Corner Number: N/A

1. History of Corner Establishment and Subsequent Restoration: Originally set by G.L.O. Surveyor, Robert F. Whitham, during 1903 survey.

2. Description of Evidence Found:

2 B.T.'s

1 47" fir snag, 50 feet tall at N61°W - 21.1 feet.

1 40" hemlock stub, at 57°W - 48.8 feet.



3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.23A, Page No. 56. Date of work 9-14-83.

Shown on D.N.R. F.M. #489

See corner diagram on reverse side.

Set std. D.N.R. concrete monument with stamped brass cap from 2 found B.T.'s.

Washington Plane Coordinates: South Zone, Y 166,117.06, X 1,616,533.21
Third Order Accuracy. Derived from ties to "Swanberg Photo Control" Tgt's 100 & 101.
Pin Pointed on Photo No. _____, Date _____, Located at _____.

SURVEYOR'S CERTIFICATE


This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.
Date 2-6-84.

Signature

21490

Certificate No.


[Seal]



AUDITOR'S CERTIFICATE

Filed for record this 9th day of FEBRUARY 1984 at 115 P.M.
In Book 3/6 of MONUMENTS at page 36 at the request
of Washington State Department of Natural Resources.

J. M. Olson Jr.
County Auditor



North. G.L.O. 1903
 64.65 CH. Creek 56. wide west
 64.95 Hem. Post, from which
 40" Dead Hemlock S7W 74L.
 40" Dead fir N61 1/4 W 32L
 Township
 Section Corner: T. 4 N. R. 34
 T. 3 N. R. 1 E.
 Found: Burned fir snag
 47" dia, 50 ft. tall N61W,
 21.1 feet no scribe
 Remaining 40" Hem. stub
 now 2 ft. high & very decayed
 S7W 48.8 feet. No scribe

Set Conc. Man. w/cap flush with mound
 of stones at foot of steep slope