

# LAND CORNER RECORD

Skamania

County

T. 4 N. R. 7E, W.M.

Corner Code No. P-13

Segregated Surveys:

Name: One-quarter corner

Corner No.:

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

## 1. History of Corner Establishment and Subsequent Restoration:

Corner originally set by Deputy Jacob Richardson during July & August 1895 under contract No. 457.

Set post

Marked 40" Fir N32E-39 lks..

30" Fir S60W-38 lks..

## 2. Description of Evidence Found:

3/4" Iron pipe set by Olson Engineering.

Orig. 40" now 48" sawed D-Fir stump N32E-39 lks. (to face) scribing visible.

Orig. 30" now rotted D-Fir mound S60W-38 lks..

Steel fence post West.

## 3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. Page No. Date of work

Set 2 1/2"x30" Aluminum pipe with a 2 1/2" Aluminum cap. -Buried pipe next to monument.

New BT's:

12" Hemlock N9W-31.8 ft. scribed 1/8" S22BT and with a 3/4" Brass disk stamped PLS 16337.

12" D-Fir S15E-43.2 ft. scribed 1/8" S21BT and with a 3/4" Brass disk stamped PLS 16337.

Set guard post East with decal survey marker only. Nailed 54-4 and BT signs to BT's and painted band and blazes red.

Stamped:

T4N R7E

S21 S22

1983

PLS 16337



Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

### SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date: 2/9/84

Signature: Larry P. Bishop

Certificate No. 16337



97148

### AUDITOR'S CERTIFICATE

Filed for record this 6th day of FEBRUARY 1984 at 12:35 P.M. In Book 4/7 of MONUMENTS at page 89 at the request of BISHOP SURVEYING, INC.

J.M. Olson by J. Davis, Dep. County Auditor