

97320

LAND CORNER RECORD

T. 3 N. R. 8E, W.M. Skamania County
 Segregated Surveys: Corner Code No. A-2
 Name: West one-sixteenth W.C.
 Corner No.: W 1/16
 DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

N/A

2. Description of Evidence Found:

N/A

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 2 Page No. 3 Date of work 3/84

Corner falls in Panther creek set W.C. S86-39-06W - 95.59 ft.. Marked: PLS 16337
 Grouted 3" Brass cap in drill hole in rock. W.C.

Chisled XBO on top of 3'x3'x5" above ground boulder
 S84W-9.0 ft. to X. W 1/16 →

Chisled XBO on top of 4'x3'x4" boulder S22E-14.8 ft. to X. T3N R8E

Set guard post West with decal survey marker only and
 post North on line with decal 54-2 only.

Painted chisled areas red. 1984



Washington Plane Coordinates: Zone, Y, X
 Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or
 under my direction in compliance with the provisions of Chapter
 50, Laws of 1973. Date MAR 12, 1984

Signature

Certificate No. 16337



AUDITOR'S CERTIFICATE

Filed for record this 23 day of Mar 1984 at 12:15 P.M. In
 Book 3/8 of Monuments at page 77 at the request of

Shirley M. Chard
 County Auditor

97320

LAND CORNER RECORD

T. 3 N, R. 8E, W.M. Skamania County
 Segregated Surveys: Corner Code No. A-2
 Name: West one-sixteenth W.C. Corner No.: W 1/16
 DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

N/A

2. Description of Evidence Found:

N/A

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 2 Page No. 3 Date of work 3/84

Corner falls in Panther creek set W.C. S86-39-06W - 95.59 ft.. Marked: PLS 16337
 Grouted 3" Brass cap in drill hole in rock. W.C.

Chisled XBO on top of 3'x3'x5' above ground boulder
 S84W-9.0 ft. to X. W 1/16 →

Chisled XBO on top of 4'x3'x4' boulder S22E-14.8 ft. to X. S6

T3N R8E
 1984

Set guard post West with decal survey marker only and
 post North on line with decal 54-2 only.

Painted chisled areas red.



Washington Plane Coordinates: Zone, Y, X
 Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or
 under my direction in compliance with the provisions of Chapter
 50, Laws of 1973. Date MAR. 12, 1984

Signature

Certificate No. 16337



AUDITOR'S CERTIFICATE

Filed for record this 23 day of Mar 1984 at 12:15 P.M. In
 Book 318 of Monuments at page 77 at the request of

Larry D. Bishop

Shirley M. Chord
 County Auditor