

97331

LAND CORNER RECORD

T 3 N, R 8E, W.M. Skamania County Corner Code No. B-3
Segregated Surveys: one-sixteenth corner
Name: Corner No.: CN 1/16
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

N/A

2. Description of Evidence Found:

N/A

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 2 Page No. 14 Date of work 3/84

Set 2 1/2" x 30" Aluminum pipe with a 2 1/2" Aluminum cap. Marked: T3N R8E
New Bearing Trees:
18" D-Fir S34 1/2 W-10.9 ft. scribed CN1/16S6BT and with a 3/4" Brass disk stamped PLS 16337. N 1/16 S6
14" D-Fir N15E-11.1 ft. scribed CN1/16S6BT and with a 3/4" Brass disk stamped PLS 16337. 1984 PLS 16337
Set guard posts East and South with decals 54-2 and survey marker.
Nailed 54-9 and BT signs to BT's and painted band and blazes red.




Washington Plane Coordinates: Zone, Y, X
Order Accuracy. Derived From:
Pin Pointed on Photo No. Date Located at.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date MAR 17, 1984

Signature Larry D. Bishop Certificate No. 16337



AUDITOR'S CERTIFICATE

Filed for record this 23 day of Mar 1984 at 12:15 P.M. In Book 3/8 of Monument at page 78 at the request of

Signature Larry M. Olson County Auditor

97321

LAND CORNER RECORD

T 3 N, R. 8E, W.M. Skamania County
 Segregated Surveys: Corner Code No. B-3
 Name: one-sixteenth corner Corner No.: CN 1/16
 D.L.C. HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

N/A

2. Description of Evidence Found:

N/A

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 2 Page No. 14 Date of work 3/84

Set 2 1/2"x30" Aluminum pipe with a 2 1/2" Aluminum cap. Marked: T3N R8E
 New Bearing Trees: C
 18" D-Fir S34 1/2 W-10.9 ft. scribed CN1/16S6BT and N 1/16 S6
 with a 3/4" Brass disk stamped PLS 16337. C
 14" D-Fir N15E-11.1 ft. scribed CN1/16S6BT and 1984
 with a 3/4" Brass disk stamped PLS 16337. PLS 16337
 Set guard posts East and South with decals 54-2
 and survey marker.
 Nailed 54-9 and BT signs to BT's and painted band and blazes red.




Washington Plane Coordinates: Zone, Y X
 Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date MAR 17, 1984

Signature *Larry D. Bishop* Certificate No. 16337



AUDITOR'S CERTIFICATE

Filed for record this 23 day of Mar 1984 at 12:15 P.M. In Book 3/8 of Monument at page 78 at the request of

Signature *Larry D. Bishop*
 Signature *Larry M. Chase* County Auditor