

97627

RES 20-1808(9-77)

4/7 93

# LAND CORNER RECORD

T. 4 N. R. 7E, W.M. Skamania County Corner Code No. 25


Segregated Surveys: Name: Section Corner Corner No.: Section  
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

### 1. History of Corner Establishment and Subsequent Restoration:

Corner originally established by Deputy Jacob Richardson under contract No. 457 during July 1895 marked:  
8" Fir S71W-34 lks..  
18" Cedar N52-30W-81 lks..

### 2. Description of Evidence Found:

Olson 3/4" pipe in talus rock slide.  
Orig. 24" now 48" D-Fir S18W-160 lks. chopped out blaze.



### 3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record: Surveyor's Field Book No. 2 Page No. 18 Date of work April 1984

Set 2 1/2" x 30" Aluminum pipe with a 2 1/2" Aluminum cap in a mound of stone. Marked: T4N R7E S25 S36 R7E 1984 PLS 16337  
Chisled XBO on top of 3'x1'x2" boulder N69W-14.3 ft. to X.

Set guard post with decal "survey marker" only.  
Nailed 54-4 and BT signs to BT's and painted band and blazes red.

Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date. Located at.

### SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date April 19, 1984

Signature: Larry D. Bishop Certificate No. 16337



### AUDITOR'S CERTIFICATE

Filed for record this 23rd day of MAY 1984 at 1:55 P.M. In Book 472 of MONUMENTS at page 23 at the request of LARRY D. BISHOP

County Auditor: [Signature]