

RES 20-1808(9-77)

LAND CORNER RECORD

SKAMANIA County
 T 7 N, R 5E, W.M. Corner Code No. Q/R 9
 Segregated Surveys:
 Name: South South 1/64 Section 20/21 Corner No.: SS 1/64 S20/21
 D.L.C., H.E.S., Tract, Mining Claim, Indian Allotment, Federal Reserve, Townships.


1. History of Corner Establishment and Subsequent Restoration:

NONE

2. Description of Evidence Found:

NONE

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 259-C Page No. 16 Date of work 8-9-84



Set a 2 1/2" x 30" Aluminum Pipe, 26" in the ground with an aluminum cap. No stone available within 250' for stone mound. Cleared a 12' circle around monument.

Painted a 6" orange band around all BT's and painted faces.

Attached USFS 54-3 and 54-9 signs on all BT's

Nailed brass survey washers IS 20898 in the top circle of newly scribed "B"'s and also a point of measurement on side of trees.

Washington Plane Coordinates: Zone, Y
 Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date August 10, 1984

Signature

20898
Certificate No.

AUDITOR'S CERTIFICATE

Filed for record this 23 RD day of AUGUST 1984 at 11:30 A.M. In Book 215 of MONUMENTS at page 21 at the request of

Recorded
 Indexed
 Filed

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.