

99914

WEYERHAEUSER COMPANY BOOK 4/5 PAGE 13

LONGVIEW AREA

LAND CORNER RECORD

SKAMANIA

County

Corner Code No. CD-1

T 4 N. R 5 E W.M.

Segregated Surveys:

Name

Corner No.:

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration: GLO Oct 20, 1897
CHARLES A. HOMAN U.S. DEPUTY SURVEYOR.

2. Description of Evidence Found: BLM BRASS CAP MONUMENT 1966: Fence Post

36" FIR N53E 10.02 BT GLO 12" BALSAM 15.85 9.9

31" FIR N38W 15.40 BT " 11" " N38W 23.85 15.18

BOTH TREES HAVE HEALED FALES. DISTANCE TO CENTER OF TREE

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 1-83 Page No. 8 Date of work 28 April 1983


☐ PLASTIC REFERENCE PLATEO 16d nail on South Side
in center of tree54-4 SIGN ON BACKS OF
TREES. 6" BLUE PAINT
BAND.

Iron Fence Post 0.5' North

Garrisonite Post 2.0' North

1" Iron pipe lying on ground.

Corner lies on 10% South slope.



Washington Plane Coordinates:

Order Accuracy. Derived From:

Pin Pointed on Photo No.

Date

Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or
 under my direction in compliance with the provisions of Chapter
 50, Laws of 1973. Date 29 JUNE 83

Signature Archie B. CarpenterCertificate No. 4516196

AUDITOR'S CERTIFICATE

Filed for record this 11th day of SEPTEMBER
 Book 4/5 of MONUMENTS

1985 at 2:25 P.M. In
 at page 13 at the request of

ARCHIE B. CARPENTER

AM Olson by J. P. New, Dep.
 County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 6 (2),
 Chapter 50, Laws of 1973.