State of Washington DEPARTMENT OF NATURAL RESOURCES BUREAU OF SURVEYS AND MAPS LAND CORNER RECORD

31 | 32 6 | 5

Skamania County

T 5 N, R 5, W.M.

Corner Code No. A-5

Segregated Surveys:

Name: n/a

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally established in 1909 by GLO surveyor C. Frank Rhodes, with a stone and 4 BTs.

No subsequent restoration found.

2. Description of Evidence Found:

GLO stone with proper notches.
40" fir BT snag at S17W 62.5 feet.
42" fir BT snag at N28W 36.4 feet.
Rotted hemlock BT stump at S53E 33.6 feet.
Rotted hemlock BT stump at N53E 34.0 feet.

FILED FOR RECORD SKANAN ETG. WASH BY

Dec | 12 17 PH '86

AUDITOR GARY M. OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location.
Diagram corner and indicate meridian and reference to map of record. Surveyor's Field
Book No. 601.07, Page No. 47. Date of work June 18, 1986.

Corner is the original granite stone.

See reverse side for corner diagram.

SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date: November 18, 1986.

H. J. Rome Zand f

21490

AUDITOR'S CERTIFICATE

Filed for record this day of 19 at M.

In Book of at page at the request of Washington State Department of Natural Resources.

115

County Auditor

The corner is the granity stanc as 3 const. 120 Originally set in 1909. S. S. S. 43.50 17 18 19 Section corner of 5 TSELN RCE Found granite chone, exposure 11, with 100 200 مرم مرمة المومان المراجعة 123 368 - 1751 AND BEST Potted hambole remains a MSSE 5/7W 62.5' no serising with on on 10' des of 1280 SEL 186 1100 0 10 David 100 J 23 W a the contract of the contract 6 10 x 0 x 0 10 th sage @ 12 Fir 5009 @ i may

State of Washington DEPARTMENT OF NATURAL RESOURCES **BUREAU OF SURVEYS AND MAPS**

LAND CORNER RECORD

Skamania County

T 5 N, R 5, W.M.

Corner Code No. A-5

Segregated Surveys:

Name: n/a

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally established in 1909 by GLO surveyor C. Frank Rhodes, with a stone and 4 BTs.

No subsequent restoration found.

Description of Evidence Found:

GLO stone with proper notches. 40" fir BT snag at S17W 62.5 feet. 42" fir BT snag at N28W 36.4 feet. Rotted hemlock BT stump at S53E 33.6 feet. Rotted hemlock BT stump at N53E 34.0 feet.

FILED FOR RECORD SKAHAR WASH BY TOM LAIRD

Dec , 12 17 PH '86 Juis, pp. AUD TOR GARY H. OLSON

Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 601.07, Page No. 47. Date of work June 18, 1986.

Corner is the original granite stone.

See reverse side for corner diagram.

SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date: November 18, 1986.

H. S. homas Zand h Certificate No. Signature

21490

	AUDITOR'S CERTIFICATE							
Filed for record thi		day of	Pagources	at pag		at the	e reques	
of Washington State	Department		Threed 5 2		Coun	ty Auditor	· · · · · · · · · · · · · · · · · · ·	