

102271

BOOK 6/5 PAGE 5

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

14	13
23	24

Skamania County

T 6 N, R 5 E, W.M.

Corner Code No. N-21

Segregated Surveys:

Name: n/a

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally established in 1909 by GLO Surveyor C. Frank Rhodes with a notched stone and 1 live and 3 dead BTs.

No subsequent restoration found.

FILED FOR RECORD
SKAMANIA CO. WASH
BY _____

Dec 1 1 16 PM '86

2. Description of Evidence Found:

Original stone with proper notches.

28" fir stub BT at N18W 15.9 feet, with visible scribe.

26" cedar BT at S61W 110.8 feet, with visible scribe.

Remains of cedar BT at N67E 6.5 feet.

AUDITOR
GARY M. OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location.
Diagram corner and indicate meridian and reference to map of record. Surveyor's Field
Book No. 601.07, Page No. 57. Date of work September 10, 1985.

Replaced original stone with DNR aluminum monument with stamped cap.

See reverse side for corner diagram.

SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work
performed by me or under my direction in compliance
with the provisions of Chapter 50, Laws of 1973.
Date: November 18, 1986.

Signature

H. Thomas Laird Jr.

21490

Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this _____ day of _____ 19 _____ at _____ M.
In Book _____ of _____ at page _____ at the request
of Washington State Department of Natural Resources.

Registered *5*
Auditor *5*

County Auditor

1909

NO SET STONE WITH
ARTICLE LES NO
LESS NO HOLON / SOUTH, EAST
NO HOLON / SOUTH, EAST

12" Dead Cedar	N 69 E	10 L	460
15" Dead Hem.	S 47 ³ / ₄ E	34 L	22.49
15" Cedar	S 61 ³ / ₄ W	172 L	113.52
28" Dead Fir	N 24 W	28 L	18.48

SECTION CORNER 23.24 76N R 5E

FOUND 6X7X12 STONE WITH
SOUTH AND WEST
ENDS ON EAST SIDES


28" Fir stub w/UIS. scirp 4 ST	
26" Cedar stub scirp	Remains of dead cedar

GORDON
BRESSLER
HANLIN

9-10-85

5

BOOK 6151 PAGE 6



102271

BOOK 6/5 PAGE 5

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

14	13
23	24

Skamania County

T 6 N, R 5 E, W.M.

Corner Code No. N-21

Segregated Surveys:

Name: n/a

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally established in 1909 by GLO Surveyor C. Frank Rhodes with a notched stone and 1 live and 3 dead BTs.

No subsequent restoration found.

FILED FOR RECORD
SKAMANIA CO. WASH
BY TOM LAIRD

Dec 1 1 16 PM '86

2. Description of Evidence Found:

Original stone with proper notches.
28" fir stub BT at N18W 15.9 feet, with visible scribe.
26" cedar BT at S61W 110.8 feet, with visible scribe.
Remains of cedar BT at N67E 6.5 feet.

AUDITOR
GARY H. OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location.
Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 601.07, Page No. 57. Date of work September 10, 1985.

Replaced original stone with DNR aluminum monument with stamped cap.

See reverse side for corner diagram.

SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.
Date: November 18, 1986.

Signature

*H. Thomas Laird Jr.*21490
Certificate No.

AUDITOR'S CERTIFICATE

Filed for record this _____ day of _____ 19____ at _____ M.
In Book _____ of _____ at page _____ at the request
of Washington State Department of Natural Resources.

Registered *5*
Index *5*

County Auditor